

WIPLINE FLOAT MODEL: 3000A

SERIAL NUMBER (LEFT): 30059

SERIAL NUMBER (RIGHT): 30060

DATE OF MANUFACTURE: N/A

DATE OF INITIAL INSTALLATION: N/A

3-1-56027-117-8



YEAR 20 ____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-------------------------	---------------------------	-------------------	-----------------------------	---



APRIL 19, 2012 N 61VA HOBBS 1000.0 TACH 864.1

COMPLETED ANNUAL/200 HR INSPECTION OF FLOATS PER WIPAIRE MM INSPECTION GUIDE. COMPLETED THE FOLLOWING REPAIRS TO LH AND RH FLOATS: RESEALED SIDE COVERS AND REPLACED ALL SCREWS. REPLACED ALL DECK COVER SEALS PN 21A01567-001, -002. REPLACED BOTH WATER RUDDER BOOTS PN 3A08650-001. RESEALED BOTH NOSE BOXES BETWEEN BAYS 1 AND 2. REPLACED ALL WATER RUDDER HINGE BUSHINGS PN 03DU04. REPLACED ALL NOSE TROLLEY BLOCKS PN 3A07604-001. REPLACED ALL BRAKE DISC'S PN 164-24500 AND ALL LININGS PN 066-10500. REPLACED ALL GEAR POSITION PLACARDS PN 10A3-6338-1, -2. REPLACED ALL NOSE WHEEL BEARINGS PN A4050 AND RACES PN A4138. REPLACED OR TIGHTENED RIVETS AS NEEDED IN FLOATS. CLEANED AND TREATED HARDWARE AND PLUMBING AS NEEDED. REPLACED RH NOSE WHEEL ANTI ROTATION PIN PN 3A06476-001, WASHER PN 3A06702-003. RESECURED RH FWD STRUT BUSHING. REPLACED LH FWD UPPER STRUT BUSHING PN U0007019. REPLACED RH AFT WATER RUDDER RETRACT CABLE PN 4A08000-072 AND RIGGED. REPLACED VARIOUS PULLEY'S PN MS20219-2 AS NEEDED. REPAIRED RH BAG COMPARTMENT FORWARD LOWER FLANGE SECTION BY INSTALLING DOUBLER MADE FROM BULKHEAD ASSY PN 3A01158-225. ASSEMBLED WET. INSTALLED WIPAIRE 3000A FLOATS SN 30059 AND 30060 1AW STC SA01320CH DATED 4/29/09 AND INSTALLATION DRAWING 12D1-7323 REV E DATED 8/4/07 ON TO CESSNA A185F SN 18503393. SWUNG GEAR AND BLEED BRAKES. SERVICED RESERVOIRS AS NEEDED. LEAK CHECKED ALL FLOAT COMPARTMENTS AND SEALED AS NEEDED.

THE AIRCRAFT AIRFRAME, AIRCRAFT ENGINE, PROPELLER, OR APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER

W/O NO. 73905/73872 DATE 4/19/12

SIGNED [Signature]
PAUL G DAUPHINAIS FOR WIPAIRE, INC. CRS RJWR390K PHONE 651.451.1205

